



VOLKSWAGEN Passat: 1HNU885

Vinnumber:	WVWZZZ3CZFE042830	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	162539	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting Halogen
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/45/17/97 V LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 4 mm
	Re.L.	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	1468,61
Door F R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper moulding F R, Scratch(es), E - Replace 14,40



Wing F R, Scratch(es), 67 - Polish 0,00
No pictures to display

Wing R L, Scratch(es), Acceptable 0,00
No pictures to display

Wing R R, Scratch(es), Acceptable 0,00
No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Windscreen, Scratch(es), E - Replace 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00
No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Tyre repair kit, Missing, E - Replace 210,53




Compressor, Missing, E - Replace 0,00



Rear spoiler, Bad repair, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Chemical cleaning

150,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display