



VOLVO XC60: 1GPE099

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | YV1DZ31A1E2570685 | Versionname: | XC60 D3 Kinetic 136PK |
| First Registrationdate: | 24/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 138281 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OVER 27903 | Parking lot: | 3610 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Central consol F | |
| TV/DVD screen R | | Luggage cover | |
| TV/DVD screen F | | Front parking sensors | |
| GPS storage | | Rear parking sensors | |
| GPS storage | HD | Type of Tow bar | Tow bar removable |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |
| Sport seats | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------------|-------|--------------------------|-------|--------------------------|
| 235/60/18/107 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Uniroyal: 7 mm | Fr.R. | Uniroyal: 7 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Door F L, Bad repair, LI - Repair and paint (complete)

318,35



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Sill F R, Deformed / Strained, E - Replace

82,73



Door panel F R, Tear, E - Replace

308,74



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Protection plate M, Hole, E - Replace

181,80

