



MERCEDES C: 1JGK239

Vinnumber:	WDD2050041F120601	Versionname:	C BER 220 BlueTEC 163PK
First Registrationdate:	11/12/2014	Fiscalpower:	
Expertise Mileage:	67444	Power Kw:	120
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3729
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2073,79
--------------------------	----------------

Door panel R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper cover R M, Broken, E - Replace 131,19



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Bumper moulding F R, Scratch(es), E - Replace 14,40



Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Windscreen, Stone chip(s), Acceptable

0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rearlight L, Broken, E - Replace

114,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00





Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Tear, Smart repair 110,64



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



