



MERCEDES C180: 1KSD251

Vinnumber:	WDD2052361F203329	Versionname:	1.6 C 180 BLUETEC AVANTGARDE
First Registrationdate:	22/06/2015	Fiscalpower:	
Expertise Mileage:	164086	Power Kw:	85
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	A SERVICE OVER 2900 KM	Parking lot:	1414
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/98 Y LightMetal				
Summer tyres:	Fr.L.	Semperit: 8 mm	Fr.R.	Semperit: 8 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1388,58

Wing F R, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Brand badge, Missing, E - Replace

89,70



Door F L, Scratch(es), Acceptable

0,00



Covering interior A pillar L, Stain, Cleaning

25,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Maintenance, Maintenance, P - Check

0,00



Wing R L, Scratch(es), Acceptable

0,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), E - Replace

370,00



Door panel R L, Hole, E - Replace

114,00



Rear roof pillar covering L, Hole, Smart repair

110,64



Ceiling, Stain, Cleaning

50,00



Windscreen, Repaired, P - Check

0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rear roof pillar covering R, Hole, Smart repair

110,64

