



**AUDI A4 AVANT: 1KXH773**

Vinnumber:	<b>WAUZZZ8KXFA146686</b>	Versionname:	<b>2.0 TDI 100KW MULTITRONIC</b>
First Registrationdate:	<b>23/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>116247</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2531</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 4 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Vredestein: 4 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1491,00</b>
<b>Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Crack, E - Replace	487,20



Roof, Chemical pollution, LI - Repair and paint (complete)	481,50
--	--------

