


AUDI A4: 1HHL005

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber: | WAUZZZ8K3EA163571 | Versionname: | A4 AVANT TDie 136PK |
| First Registrationdate: | 24/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 149453 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3723 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | DVD | Luggage cover | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 205/60/16/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|--|------------|
| Emergency spare wheel | Yes |
| Number of charging cables (normal) | 0 |
| Number of charging cables (rapid charge) | 0 |

| | |
|---|----------------|
| Total cost ex VAT | 1705,45 |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



Protection plate M, Deformed / Strained, E - Replace

84,00



Bonnet, Stone chip(s), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Hole, Smart repair

64,32



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame R L, Dent(s), It - Spot repair

115,56



Rear spoiler, Dent(s), LI - Repair and paint (complete)

115,56



Rear window, Scratch(es), Acceptable

0,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Deformed / Strained, LI - Repair and paint (complete)

211,80





Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Dent(s), PDR - Paintless dent repair 63,00

