



AUDI A3: 1HPH010

Vinnumber:	WAUZZZ8V0F1048809	Versionname:	A3 SED Attraction 110PK
First Registrationdate:	4/09/2014	Fiscalpower:	
Expertise Mileage:	123088	Power Kw:	81
Bodytype:	Berline	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4229
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1264,41
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35





Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Windscreen, Repaired, Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display