



AUDI A6: 1KUH700

Vinnumber:	WAUZZZ4G0GN035978	Versionname:	2.0 TDI ULTRA 100KW S TRONIC
First Registrationdate:	7/07/2015	Fiscalpower:	
Expertise Mileage:	105507	Power Kw:	100
Bodytype:	Berline	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1304
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/60/16/98 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	583,00
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R R, Bad repair, Acceptable 0,00



Door R L, Bad repair, Acceptable 0,00



Wing F L, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00



Alloy rim F R, Deformed / Strained, E - Replace 277,44



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper cover R M, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Alloy rim R R, Rust, Acceptable	0,00
---------------------------------	------

