



BMW 4 GRAN COUPE: 1LAR358

Vinnumber:	WBA4E91050G390703	Versionname:	2.0 420D (120KW) GRAN COUPE
First Registrationdate:	4/08/2015	Fiscalpower:	
Expertise Mileage:	92060	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3525
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Total cost ex VAT			131,16
Bumper F, Dent(s) and scratch(es), Le - Replace and paint			0,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper grille F R, Broken, E - Replace 34,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Seat cover R, Stain, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Bumper grille F L, Broken, E - Replace 34,08



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Tyre repair kit, Empty, E - Replace 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display