


**FORD GRAND C-MAX: 1KJA101**

Vinnumber:	<b>WFOHXXGCBHFD50959</b>	Versionname:	<b>1.6 TDCI 85KW S/S TREND STYLE</b>
First Registrationdate:	<b>8/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>72142</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color:	<b>.</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Battery functioning:	<b>Yes</b>	Oil level:	<b>OK</b>
Number of doors:	<b>5</b>	Parking lot:	<b>3109</b>
Number of seats:	<b>6</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS base</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/16/93 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 6,5 mm</b>	Fr.R.	<b>Vredestein: 6,5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1739,55
Wing F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Headrest R R, Missing, E - Replace 60,00



Sliding door L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display


Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace 42,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper moulding F M, Broken, E - Replace 14,40



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Headrest R L, Missing, E - Replace 60,00



Rear window, Scratch(es), E - Replace

370,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20

