



**CITROEN C4 Picasso: 1JJT954**

Vinnumber:	<b>VF73A9HC8EJ843548</b>	Versionname:	<b>GR.C4 PICASSO Business 115PK</b>
First Registrationdate:	<b>6/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>165328</b>	Power Kw:	<b>85</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2728</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	<b>No Tow bar</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>No GPS</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Other: 6 mm</b>	Fr.R.	<b>Other: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	3205,80
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20





Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35




Roof, Bad repair, Acceptable

0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68







Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F R, Scratch(es), Smart repair

110,64



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

