



BMW 5 BERLINE: 1JUK485

Vinnumber:	WBA5E31070D787185	Versionname:	2.0 518D (100KW)
First Registrationdate:	27/02/2015	Fiscalpower:	
Expertise Mileage:	137670	Power Kw:	100
Bodytype:	Berline	Body color:	GRIJS
Gearbox:	Automatic	Body color:	Dark Grey
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	OK	Oil level:	OK
Maintenance:	15000 KM	Parking lot:	2713
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L. Bridgestone: 7 mm	Fr.R. Bridgestone: 7 mm	
	Re.L. Bridgestone: 6 mm	Re.R. Bridgestone: 6 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 400,56

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), Acceptable

0,00



Tailgate, Dent(s), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00




Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), 67 - Polish

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

