


FORD GRAND C-MAX: 1KFJ961

Vinnumber:	WFOHXXGCBHFD50899	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	129685	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3701
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			681,43
Bumper R, Scratch(es), Acceptable			0,00



Internal Boot Lining L, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim F R polished, Scratch(es), Acceptable

0,00



Maintenance book, Missing, E - Replace

0,00



Ignition key, Missing, E - Replace

150,00



Door F L, Scratch(es), 67 - Polish

0,00



Handbrake cover, Worn, Acceptable

0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Internal Boot Lining R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), 67 - Polish

0,00



Gear shift lever knob, Worn, Acceptable

0,00



Rear window, Scratch(es), 67 - Polish

55,19



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

