


**OPEL COMBO: 1PPX014**

|                                    |                                 |              |                               |
|------------------------------------|---------------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>W0L6ZYC1AH9603608</b>        | Versionname: | <b>1.3 CDTI 66KW 2.0T SWB</b> |
| First Registrationdate:            | <b>25/08/2016</b>               | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>38357</b>                    | Power Kw:    | <b>66</b>                     |
| Bodytype:                          |                                 | Body color:  | <b>Black</b>                  |
| Gearbox:                           | <b>MAN 5 VIT</b>                | Paint type:  | <b>Opaque</b>                 |
| Transmission:                      | <b>Front</b>                    | Rims summer: | <b>Steel</b>                  |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>2202</b>                   |
| Number of doors:                   | <b>4</b>                        |              |                               |
| Number of seats:                   | <b>2</b>                        |              |                               |
| Number head rests:                 | <b>2</b>                        |              |                               |
| Rims summer:                       | <b>Steel</b>                    |              |                               |
| Category:                          | <b>Light Commercial Vehicle</b> |              |                               |
| Oil level:                         | <b>OK</b>                       |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |                               |

**Options**

|                         |                               |                 |                   |
|-------------------------|-------------------------------|-----------------|-------------------|
| Radio CD                |                               | Type of Tow bar | <b>No Tow bar</b> |
| Windows electric F      |                               |                 |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                 |                   |
| Type of GPS             | <b>No GPS</b>                 |                 |                   |
| Type of Lining          | <b>Lining fabrics</b>         |                 |                   |
| Type of climate control | <b>Manual climate control</b> |                 |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>185/65/15/92 T Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Goodyear: 3 mm</b> | Fr.R. | <b>Goodyear: 3 mm</b> |
|               | Re.L.                       | <b>Goodyear: 3 mm</b> | Re.R. | <b>Goodyear: 3 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|  |       |
|--|-------|
| Total cost ex VAT                            | 63,00 |
| Wing F R, Scratch(es), Acceptable            | 0,00  |
| <i>No pictures to display</i>                |       |
| Bonnet, Dent(s), PDR - Paintless dent repair | 63,00 |



|   |      |
|---|------|
| Bodywork, Not original part, Acceptable | 0,00 |
| <i>No pictures to display</i>           |      |
| Bumper R, Scratch(es), Acceptable       | 0,00 |
| <i>No pictures to display</i>           |      |
| Sidewall RL (LCV), Dent(s), Acceptable  | 0,00 |
| <i>No pictures to display</i>           |      |