



OPEL COMBO: 1PPX033

Vinnumber:	W0L6ZYC1AH9603247	Versionname:	1.3 CDTI 66KW 2.0T SWB
First Registrationdate:	25/08/2016	Fiscalpower:	
Expertise Mileage:	51647	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2119
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 T Steel			
Summer tyres:	Fr.L. Pirelli: 5 mm	Fr.R. Pirelli: 5 mm	
	Re.L. Pirelli: 5 mm	Re.R. Pirelli: 5 mm	

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	746,72
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76



Sidewall RL (LCV), Dent(s) and scratch(es), It - Spot repair

115,56



Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Hole, E - Replace

329,40

