


FORD C-MAX: 1KLE234

Vinnumber:	WF0JXXGCBJFD82993	Versionname:	1.6 TDCI 85KW S/S TITANIUM STYLE
First Registrationdate:	26/05/2015	Fiscalpower:	85
Expertise Mileage:	109780	Power Kw:	85
Bodytype:		Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Black
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	2104
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	642,54
Door F R, Scratch(es), Acceptable	0,00



Wing R R, Chemical polution, Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Sill outer R, Scratch(es), It - Spot repair

115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

