



VOLKSWAGEN GOLF VII: 1KUF814

Vinnumber:	WVWZZZAUZFP102871	Versionname:	1.6 TDI 77KW BMT TRENDLINE
First Registrationdate:	6/07/2015	Fiscalpower:	
Expertise Mileage:	164687	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	16.800 KM OU 247 JOURS	Parking lot	3707
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	198,36
-------------------	--------

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), It - Spot repair	115,56
---	--------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair	82,80
--	-------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display