


RENAULT Grand Scenic: 1HHY826

Vinnumber:	VF1JZ14M651486622	Versionname:	GRAND SCENIC Authentique 5pl.110PK
First Registrationdate:	29/07/2014	Fiscalpower:	
Expertise Mileage:	109527	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4424
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	888,95
-------------------	--------

Rearview mirror L complete, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Rocker panel inner R L, Dent(s), Acceptable	0,00
---	------

No pictures to display

Dent(s), Dent(s) and scratch(es), L.L. Dent(s) and paint (complete)	210,25
---	--------




Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair

58,80



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Dent(s), Acceptable

0,00

No pictures to display

Mirror side blinker L, Deformed / Strained, E - Replace

30,00



Luggage space cover, Missing, E - Replace

240,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover F R, Scratch(es), E - Replace

30,00

