



**VOLKSWAGEN Caddy: 1GJA057**

Vinnumber:	<b>WV1ZZZ2KZEX101691</b>	Versionname:	<b>CADDY VAN B/F 75PK</b>
First Registrationdate:	<b>20/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>123681</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4712</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Cruise Control			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 2 mm</b>	Fr.R.	<b>Michelin: 2 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>1056,19</b>
Windscreen, Repaired, Acceptable	<b>0,00</b>



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Handbrake cover, Broken, E - Replace 15,00



Bumper R, Scratch(es), Smart repair 110,64



Interior, Dirty, Cleaning 50,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Hole, E - Replace 300,00



Inner seat cover R, Broken, Smart repair 110,64



Trunk door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display

Trunk door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display