



LU Volkswagen Passat: GP4079

Vinnumber:	WVWZZZ3CZGE125148	Versionname:	1.6 TDI 88KW COMFORTLINE BMT
First Registrationdate:	10/12/2015	Fiscalpower:	
Expertise Mileage:	110350	Power Kw:	88
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1112
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/94 V LightMetal			
Summer tyres:	Fr.L. Pirelli: 6 mm	Fr.R. Pirelli: 6 mm	
	Re.L. Pirelli: 7 mm	Re.R. Pirelli: 7 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2137,95
--------------------------	----------------

Alloy rim F R polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair	82,80
---	--------------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Mirror side blinker R, Scratch(es), Acceptable 0,00

No pictures to display


Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Dent(s), LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 481,50



Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display