



**VOLVO V60: 1KLE267**

|                                    |                              |              |                       |
|------------------------------------|------------------------------|--------------|-----------------------|
| Vinnumber:                         | <b>YV1FW8481F1268980</b>     | Versionname: | <b>1.6 D2 KINETIC</b> |
| First Registrationdate:            | <b>26/05/2015</b>            | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>68805</b>                 | Power Kw:    | <b>84</b>             |
| Bodytype:                          |                              | Body color:  | <b>Red</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>             | Paint type:  | <b>Metallic</b>       |
| Transmission:                      | <b>Front</b>                 | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>                | Oil level:   | <b>OK</b>             |
| Maintenance:                       | <b>SERVICE IN 13005KM 8M</b> | Parking lot: | <b>4721</b>           |
| Maintenance:                       | <b>OK</b>                    |              |                       |
| Battery functioning:               | <b>Yes</b>                   |              |                       |
| Number of doors:                   | <b>5</b>                     |              |                       |
| Number of seats:                   | <b>5</b>                     |              |                       |
| Number head rests:                 | <b>5</b>                     |              |                       |
| Rims summer:                       | <b>Aluminium</b>             |              |                       |
| Category:                          | <b>Passenger Car</b>         |              |                       |
| Oil level:                         | <b>OK</b>                    |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>                   |              |                       |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                          |
| GPS storage                    |                              | Rear parking sensors |                          |
| Windows electric F             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |                              |                      |                          |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/96 H LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                                  | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 306,80 |
|-------------------|--------|

|                             |      |
|-----------------------------|------|
| Bonnet, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

|   |        |
|---|--------|
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*