



**VOLVO V60: 1KVD281**

Vinnumber:	<b>YV1FW78C0G1293919</b>	Versionname:	<b>2.0 D2 GEARTRONIC KINETIC</b>
First Registrationdate:	<b>10/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>84217</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>PLUS 26445 KM</b>	Parking lot:	<b>4513</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/16/97 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Firestone: 6 mm</b>	Fr.R.	<b>Firestone: 6 mm</b>
	Re.L.	<b>Firestone: 7 mm</b>	Re.R.	<b>Firestone: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>259,32</b>
Alloy rim F L, Scratch(es), Acceptable			<b>0,00</b>



Wing R R, Scratch(es), Acceptable

0,00



Door panel F L, Scratch(es), Acceptable

0,00



Door frame R R, Scratch(es), Acceptable

0,00



Floor covering F L, Burned, Smart repair

64,32



Outer door handle F R, Scratch(es), Acceptable

0,00



Door panel R R, Scratch(es), Acceptable

0,00



Bonnet, Dent(s), Acceptable

0,00



Ceiling, Stain, Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Door panel R L, Scratch(es), Acceptable

0,00



Wing R L, Repaired, No repair

0,00



Bumper F, Scratch(es), Acceptable

0,00



Interior, Stain, Cleaning

100,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame R L, Scratch(es), Acceptable

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

