



SKODA OCTAVIA COMBI: 1KCG294

Vinnnummer:	TMBJG7NE6F0207983	Versionname:	1.6 CRTDI 81KW GREENLINE AMBITION
First Registrationdate:	31/03/2015	Fiscalpower:	
Expertise Mileage:	173280	Power Kw:	81
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4602
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1913,70
Backrest cover F L, Hole, E - Replace	360,00



Rearview mirror housing R, Broken, E - Replace 104,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Sill outer L, Dent(s), LI - Repair and paint (complete) 310,50




Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Dent(s), LI - Repair and paint (complete) 406,50



Door R R, Dent(s), LI - Repair and paint (complete) 414,35

