


SKODA Octavia: 1GFE031

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | TMBJG7NE9E0136907 | Versionname: | OCTAVIA COMBI Ambition 105PK |
| First Registrationdate: | 22/01/2014 | Fiscalpower: | |
| Expertise Mileage: | 168896 | Power Kw: | 77 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3212 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Windows electric R | Luggage cover |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| | Tow bar removable |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 205/55/16/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|-----------------------------------|---------|
| Total cost ex VAT | 1163,80 |
| Tailgate, Hail damage, PDR - Hail | 100,00 |



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair 63,00



Roof, Hail damage, PDR - Hail 375,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight L, Broken, E - Replace 114,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Hail damage, PDR - Hail 300,00

