



BMW 1 HATCH: HD0686

Vinnumber:	WBA1U510705B74333	Versionname:	2.0 118D XDRIVE (110KW)
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	88157	Power Kw:	110
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3208
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/40/17/91 W LightMetal			
Summer tyres:	Fr.L. Continental: 6 mm	Fr.R. Continental: 6 mm	
	Re.L. Bridgestone: 4 mm	Re.R. Bridgestone: 4 mm	

Assistance equipment

Total cost ex VAT	613,60
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Bad repair, Acceptable

0,00

