



BMW X3: 1LRU502			
Vinnumber:	WBAWZ310900F65959	Versionname:	2.0 SDRIVE18D (100KW)
First Registrationdate:	17/11/2015	Fiscalpower:	
Expertise Mileage:	55746	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2314
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	225/60/17/99 V LightMetal		
	Fr.L. Dunlop: 6 mm	Fr.R. Dunlop: 6 mm	
	Re.L. Pirelli: 3 mm	Re.R. Pirelli: 3 mm	

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1247,32
Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)			264,21



Roof, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
Wing R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), PDR - Paintless dent repair	63,00
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
Door F R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Bonnet, Dent(s), LI - Repair and paint (complete)	348,09
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
Tailgate, Bad repair, Acceptable	0,00

