



MERCEDES A: 1KSJ417

Vinnumber:	WDD1760111V086336	Versionname:	1.5 A 160 CDI
First Registrationdate:	23/06/2015	Fiscalpower:	
Expertise Mileage:	68456	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3232
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT 774,36

Wing R L, Repaired, Acceptable 0,00



Roof, Dent(s), PDR - Paintless dent repair

63,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Door R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Repaired, Acceptable

0,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display

Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00



Centre console, Scratch(es), Acceptable

0,00





Rearview mirror L complete, Broken, E - Replace 168,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door seal F L, Deformed / Strained, Acceptable 0,00

No pictures to display

Wheel cover F L, Broken, E - Replace 30,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Paintless dent repair 63,00



MOT Certificate, Missing, Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80





Bumper R, Dent(s), It - Spot repair 115,56



Wheel cover F R, Broken, E - Replace 30,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display