



BMW 3: 1HSC091

Vinnumber:	WBA3K910X0F936275	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	18/09/2014	Fiscalpower:	
Expertise Mileage:	132181	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2301
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	909,56
-------------------	---------------

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Deformed / Strained, E - Replace 62,00



Door seal R L, Broken, E - Replace 54,00



Windscreen, Repaired, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Maintenance, Maintenance, Execute 0,00

No pictures to display