


MERCEDES A 180: 1KDX084

Vinnumber:	WDD1760121V067145	Versionname:	CDI
First Registrationdate:	10/04/2015	Fiscalpower:	
Expertise Mileage:	64936	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4503
Maintenance:	B5 - 59 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT 1749,59

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance, Maintenance, Execute

0,00



Seat cover F L, Stain, Cleaning

25,00



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

210,53



Seat cover F L, Worn, P - Check

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F R, Stain, Cleaning

25,00



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Door panel F L, Worn, Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,35





Covering interior A pillar L, Hole, E - Replace 38,76



Seat cover R, Stain, Cleaning 25,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair 63,00

