



OPEL Insignia: 1HCR955

Vinnumber:	WOLGM8ER2E1137269	Versionname:	INSIGNIA BRE ecoFL.Business 120PK
First Registrationdate:	19/06/2014	Fiscalpower:	
Expertise Mileage:	103783	Power Kw:	88
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4110
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1433,94

Tailgate, Bad repair, LI - Repair and paint (complete) 301,68



Door R L, Bad repair, LI - Repair and paint (complete) 318,35



Alloy rim F L polished, Rust, LI - Repair and paint (complete) 95,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Bad repair, LI - Repair and paint (complete) 115,56



Alloy rim F R polished, Rust, LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00



Door F R, Bad repair, LI - Repair and paint (complete) 318,35



Alloy rim R L polished, Rust, LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Rust, LI - Repair and paint (complete) 95,00

