



**MERCEDES CLA SHOOTING BRAKE: 1KLE250**

Vinnnummer:	<b>WDD1179081N229311</b>	Versionname:	<b>2.1 CLA 200 CDI SHOOTING BRAKE</b>
First Registrationdate:	<b>26/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>90726</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>BIN 280 DAGEN</b>	Parking lot:	<b>2206</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Type of Tow bar
Windows electric F	No Tow bar
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Manual climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 7 mm</b>	Fr.R.	<b>Vredestein: 7 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>274,80</b>
Door R R, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing F R, Dent(s), Acceptable			<b>0,00</b>

<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s), PDR - Paintless dent repair	63,00



Wing R R, Repaired, Acceptable	0,00
--------------------------------	------



Seat cover F L, Worn, P - Check	0,00
---------------------------------	------

