


FORD KUGA: 1KBK926

Vinnumber:	WF0AXXWPM AFC56733	Versionname:	2.0 TDCI 2WD 88KW TITANIUM
First Registrationdate:	25/03/2015	Fiscalpower:	
Expertise Mileage:	103656	Power Kw:	88
Bodytype:		Body color	GROEN
Gearbox:	MAN 6 VIT	Body color	Green
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	GEEN MELDING PCONTROLER	Oil level	OK
Maintenance	OK	Parking lot	1704
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/55/17/103 V LightMetal				
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	321,20
-------------------	---------------

Wings trim P.L. Scratch(es). Acceptable	0,00
---	-------------

wing trim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door frame R L, Dent(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Tailgate, Scratch(es), It - Spot repair	115,56
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper cover R M, Scratch(es), Smart repair	110,64
---	--------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Wing trim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display