



**MERCEDES CLA SHOOTING BRAKE: 1KPF187**

Vinnumber:	<b>WDD1179081N230996</b>	Versionname:	<b>2.1 CLA 200 CDI URBAN SHOOTING BRAKE</b>
First Registrationdate:	<b>9/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>160406</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>VIOLET</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Purple</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>SERVICE A1 IN 14500KM</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>1528</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>1</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	
Sport seats		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/17/91 W LightMetal</b>			
Summer tyres:	Fr.L. <b>Bridgestone: 6 mm</b>	Fr.R. <b>Bridgestone: 6 mm</b>	
	Re.L. <b>Bridgestone: 7 mm</b>	Re.R. <b>Bridgestone: 7 mm</b>	

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>306,80</b>
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Alloy rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

