


OPEL VIVARO: 1UQG990

| | | | |
|------------------------------------|---------------------------------|--------------|--|
| Vinnumber: | W0VF7G606JV621081 | Versionname: | 1.6 CDTI 90kW L1H1 2.7T Edition |
| First Registrationdate: | 6/07/2018 | Fiscalpower: | |
| Expertise Mileage: | 38287 | Power Kw: | 88 |
| Bodytype: | Transporter | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1314 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|-------------------------|-------------------------------|
| Windows electric F | Central consol F |
| Cruise Control | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Manual climate control |
| | Tow bar fixed |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|------------------------------|-------|-----------------------|-------|-----------------------|
| 205/65/16/107 T Steel | | | | |
| Summer tyres: | Fr.L. | Goodyear: 7 mm | Fr.R. | Goodyear: 7 mm |
| | Re.L. | Goodyear: 7 mm | Re.R. | Goodyear: 7 mm |

Assistance equipment

| | |
|-------------|------------|
| Spare wheel | Yes |
|-------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 274,14 |
|-------------------|--------|

| | |
|--|------|
| Instruction book, Missing, E - Replace | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Maintenance book, Missing, E - Replace | 0,00 |
|--|------|

No pictures to display

| | |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display

| | |
|--|--------|
| Rearview mirror housing R, Scratch(es), Smart repair | 110,64 |
|--|--------|



| | |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Rearview mirror glass R, Broken, E - Replace | 13,50 |
|--|-------|

