


**AUDI A4 AVANT: 1KPH622**

|                                    |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WAUZZZ8K9FA119639</b> | Versionname: | <b>2.0 TDI ULTRA 100KW</b> |
| First Registrationdate:            | <b>9/06/2015</b>         | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>123627</b>            | Power Kw:    | <b>100</b>                 |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metallic</b>            |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2311</b>                |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Seats F heated                 | <b>No Tow bar</b>            |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>205/60/16/92 V LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|                                  | Re.L. | <b>Bridgestone: 4 mm</b> | Re.R. | <b>Bridgestone: 4 mm</b> |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|   |                |
|---|----------------|
| Total cost ex VAT   | <b>1874,16</b> |
| Roofrack, Scratch(es), Acceptable                         | <b>0,00</b>    |
| <i>No pictures to display</i>                             |                |
| Bumper F, Dent(s) and scratch(es), Le - Replace and paint | <b>735,00</b>  |



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Boot carpet, Stain, Chemical cleaning

25,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Windscreen, Stone chip(s), Windscreen repair

58,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

