


RENAULT Clio: 1EJR596

Vinnumber:	VF15RJL0H48168497	Versionname:	CLIO IV BER e-Business St&St 90PK
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	79575	Power Kw:	66
Bodytype:	Hatchback	Body color:	Burgundy
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	4614
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2102,77
Wing R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Sidewall panel RR, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F R, Broken, E - Replace	24,00



Window F L door, Scratch(es), 67 - Polish 55,19



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 217,44



Wheel cover F L, Scratch(es), E - Replace 24,00



Bumper R, Scratch(es), 67 - Polish 0,00

No pictures to display

Seat cover F L, Dirty, Cleaning 25,00



Bonnet, Dent(s), LI - Repair and paint (complete) 280,06



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 385,20





Door R L, Dent(s), PDR - Paintless dent repair

63,00



Internal Boot Lining L, Scratch(es), Smart repair

110,64



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Seat cover F R, Dirty, Cleaning

25,00



Wheel cover R L, Scratch(es), E - Replace

24,00



Seat cover R R, Dirty, Cleaning

25,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Ceiling, Scratch(es), Smart repair

64,32



Wheel cover R R, Scratch(es), E - Replace

24,00

