



VOLKSWAGEN Passat: 1HNZ717

Vinnumber:	WVWZZZ3CZFE041423	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	2/09/2014	Fiscalpower:	
Expertise Mileage:	193524	Power Kw:	77
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2527
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Sun Roof electric	
Windows electric R	Panoramic roof	
Cruise Control	Central consol F	
Steering wheel multifunctional	Luggage cover	
Seats F heated	Front parking sensors	
Type of headlighting	Rear parking sensors	
Type of GPS	Type of Tow bar	Tow bar fixed
Type of Lining		
Type of climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/55/16/97 W LightMetal			
	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Total cost ex VAT			921,58
Certificate Of Conformity, Missing, E - Replace			150,00
No pictures to display			
Door F L, Scratch(es), Acceptable			0,00
No pictures to display			
Seat cover F L, Worn, Acceptable			0,00



Full screen GPS, Missing, E - Replace	0,00
---------------------------------------	------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display