


BMW 3: 1HSD016

Vinnumber:	WBA3D91030J220499	Versionname:	3 BER 316dA 116PK Aut.
First Registrationdate:	18/09/2014	Fiscalpower:	
Expertise Mileage:	136133	Power Kw:	85
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3128
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			840,24
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper moulding F, Broken, E - Replace			14,40



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rocker panel inner R L, Scratch(es), Forfeit	115,56
--	--------



Tyre R L, Flat, E - Replace	132,00
-----------------------------	--------



Engine protective plate, Hole, E - Replace	86,52
--	-------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door panel R L, Hole, Smart repair	110,64
------------------------------------	--------



Bumper F, Scratch(es), It - Spot repair	115,56
---	--------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), It - Spot repair	115,56
---	--------

