



**PEUGEOT 208: 1LEJ835**

|                                   |                   |              |                         |
|-----------------------------------|-------------------|--------------|-------------------------|
| Vinnumber:                        | VF3CCBHW6FT128643 | Versionname: | 1.6 BLUEHDI 55KW ACTIVE |
| First Registrationdate:           | 4/09/2015         | Fiscalpower: |                         |
| Expertise Mileage:                | 162795            | Power Kw:    | 55                      |
| Bodytype:                         |                   | Body color   | Silver                  |
| Gearbox:                          | MAN 5 VIT         | Paint type   | Metalic                 |
| Transmission:                     | Front             | Rims summer  | Steel                   |
| Fueltype:                         | Diesel            | Oil level    | OK                      |
| Battery functioning               | Yes               | Parking lot  | 4812                    |
| Number of doors                   | 5                 |              |                         |
| Number of seats                   | 5                 |              |                         |
| Number head rests                 | 5                 |              |                         |
| Rims summer                       | Steel             |              |                         |
| Category                          | Passenger Car     |              |                         |
| Oil level                         | OK                |              |                         |
| Registration Certificate Car (BE) | Yes               |              |                         |

**Options**

|                                |                        |
|--------------------------------|------------------------|
| Windows electric F             | Luggage cover          |
| Cruise Control                 | Rear parking sensors   |
| Steering wheel multifunctional | Type of Tow bar        |
| Radio multimedia               | No Tow bar             |
| Type of headlighting           | Headlighting Halogen   |
| Type of GPS                    | GPS big screen color   |
| Type of Lining                 | Lining fabrics         |
| Type of climate control        | Manual climate control |

**Limited Technical Inspection**

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

**Degree of wear**

|               |                      |             |       |             |
|---------------|----------------------|-------------|-------|-------------|
| Winter tyres: | 185/65/15/88 T Steel |             |       |             |
|               | Fr.L.                | Fulda: 4 mm | Fr.R. | Fulda: 4 mm |
|               | Re.L.                | Fulda: 4 mm | Re.R. | Fulda: 4 mm |
|               |                      |             |       |             |

**Assistance equipment**

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

|                                                         |        |
|---------------------------------------------------------|--------|
| Total cost ex VAT                                       | 755,88 |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 169,44 |



|                                                                                                                                                                                                                                                             |  |        |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------|
| Rear window, Scratch(es), E - Replace                                                                                                                                                                                                                       |  | 320,00 |
|                                                                                             |  |        |
| Wheel cover F R, Scratch(es), E - Replace                                                                                                                                                                                                                   |  | 24,00  |
|                                                                                           |  |        |
| Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)                                                                                                                                                                                         |  | 194,44 |
|          |  |        |
|                                                                                                                                                                            |  |        |
| Trunk lid covering R, Scratch(es), Acceptable                                                                                                                                                                                                               |  | 0,00   |
| No pictures to display                                                                                                                                                                                                                                      |  |        |
| Door R L, Scratch(es), Acceptable                                                                                                                                                                                                                           |  | 0,00   |
| No pictures to display                                                                                                                                                                                                                                      |  |        |
| Wheel cover F L, Scratch(es), E - Replace                                                                                                                                                                                                                   |  | 24,00  |
|    |  |        |
| Wheel cover R R, Scratch(es), E - Replace                                                                                                                                                                                                                   |  | 24,00  |
|    |  |        |
| Tailgate, Scratch(es), Acceptable                                                                                                                                                                                                                           |  | 0,00   |
| No pictures to display                                                                                                                                                                                                                                      |  |        |