


VOLKSWAGEN Passat: 1HNU904

Vinnumber:	WVWZZZ3CZFE002175	Versionname:	PASSAT VAR Comfortline 136PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	123164	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3602
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	846,60
-------------------	--------

Window R L door, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Roof, Dent(s), Acceptable	0,00
---------------------------	------

No pictures to display	
Wing F L, Dent(s), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Dent(s), PDR - Paintless dent repair	360,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Roof pillar L, Dent(s), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Dent(s), PDR - Paintless dent repair	63,00

