


**BMW 2 GRAN TOURER: 1LBX596**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber:                         | <b>WBA2E51020P793635</b> | Versionname: | <b>2.0 218D (100KW) GRAN TOURER</b> |
| First Registrationdate:            | <b>14/08/2015</b>        | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>101587</b>            | Power Kw:    | <b>100</b>                          |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Brown</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Maintenance:                       | <b>BINNEN 15000 KM</b>   | Parking lot: | <b>4806</b>                         |
| Maintenance:                       | <b>OK</b>                |              |                                     |
| Battery functioning:               | <b>Yes</b>               |              |                                     |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>7</b>                 |              |                                     |
| Number head rests:                 | <b>7</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| GPS storage                    | <b>HD</b>                    | Central consol F     |                          |
| GPS storage                    |                              | Luggage cover        |                          |
| Windows electric F             |                              | Rear parking sensors |                          |
| Windows electric R             |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Cruise Control                 |                              |                      |                          |
| Steering wheel multifunctional |                              |                      |                          |
| Radio multimedia               |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining leather</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |
| Adaptive cruise control        |                              |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                           |               |       |               |
|---------------|---------------------------|---------------|-------|---------------|
| Summer tyres: | 205/55/17/91 W LightMetal |               |       |               |
|               | Fr.L.                     | Hankook: 4 mm | Fr.R. | Hankook: 4 mm |
|               | Re.L.                     | Hankook: 4 mm | Re.R. | Hankook: 4 mm |

**Assistance equipment**

|                                      |                |
|--------------------------------------|----------------|
| Total cost ex VAT                    | <b>1449,00</b> |
| Windscreen, Scratch(es), E - Replace | <b>487,20</b>  |



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00






|                                |      |
|--------------------------------|------|
| Door F R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|



|                                                                       |       |
|-----------------------------------------------------------------------|-------|
| Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|-----------------------------------------------------------------------|-------|



|                           |      |
|---------------------------|------|
| Roof, Dent(s), Acceptable | 0,00 |
|---------------------------|------|

No pictures to display