



VOLKSWAGEN Passat: 1HJH377

Vinnumber:	WVWZZZ3CZFE028970	Versionname:	PASSAT VAR Highline 136PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	143428	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4615
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/45/17/94 Y LightMetal			
	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Repair kit	No	Compressor	No
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2136,79
-------------------	---------

Door frame R L, Dent(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair	110,64
---	--------



Tyre repair kit, Missing, E - Replace

210,53



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80





Door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Compressor, Missing, E - Replace	0,00



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Bonnet, Chemical polution, LI - Repair and paint (complete)	338,08
---	--------



Door R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Door F L, Dent(s), LI - Repair and paint (complete)	318,35
---	--------





Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------

