


**VOLKSWAGEN GOLF VARIANT: 1KXL473**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WVWZZZAUZGP521027</b> | Versionname: | <b>1.6 TDI 66KW TRENDLINE</b> |
| First Registrationdate:            | <b>24/07/2015</b>        | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>138543</b>            | Power Kw:    | <b>66</b>                     |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Silver</b>                 |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      |                          | Rims summer: | <b>Steel</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2315</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Steel</b>             |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional | Type of Tow bar              |
| Radio multimedia               | <b>Tow bar fixed</b>         |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |
| Adaptive cruise control        |                              |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                      |                   |       |                   |
|---------------|----------------------|-------------------|-------|-------------------|
| Summer tyres: | 185/65/15/91 H Steel |                   |       |                   |
|               | Fr.L.                | Continental: 5 mm | Fr.R. | Continental: 5 mm |
|               | Re.L.                | Hankook: 4 mm     | Re.R. | Hankook: 4 mm     |

**Assistance equipment**

|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|                                                                     |                |
|---------------------------------------------------------------------|----------------|
| Total cost ex VAT                                                   | <b>1060,30</b> |
| Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | <b>318,35</b>  |



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80

