



RENAULT Megane: 1H DU214

Vinnumber:	VF1KZ0R0251316023	Versionname:	MEGANE GT TomTom Edition 95PK
First Registrationdate:	26/06/2014	Fiscalpower:	
Expertise Mileage:	175396	Power Kw:	70
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2720
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	568,86
-------------------	---------------

Wheel cover F R, Deformed / Strained, E - Replace	30,00
---	--------------



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 30,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 82,80



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete) 115,56



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00

