



VOLKSWAGEN Touran: 1GIG474

Vinnumber:	WVGZZZ1TZEW069132	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	14/02/2014	Fiscalpower:	
Expertise Mileage:	174676	Power Kw:	77
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3122
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
-------------------	------

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	