


VOLKSWAGEN Touran: 1HUP161

Vinnnumber:	WVGZZZ1TZFW020210	Versionname:	TOURAN Highline BMT St&St 7pl.140PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	148378	Power Kw:	103
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3301
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1728,19
-------------------	---------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Armrest R L, Damaged, Smart repair	64,32
------------------------------------	-------



Wheel cover F L, Missing, E - Replace 30,00



Speaker cover R L, Scratch(es), Acceptable 0,00



Outer door handle F L, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Missing, E - Replace 30,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bad repair, Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56





Wheel cover R R, Missing, E - Replace

30,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Foglight L, Broken, E - Replace

138,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Dent(s), PDR - Paintless dent repair

82,80



