



BMW X4: 1LES425

Vinnumber:	WBAXX110900R35917	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	8/09/2015	Fiscalpower:	
Expertise Mileage:	39331	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/50/18/100 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1867,31
--------------------------	----------------

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Scratch(es), It - Spot repair	115,56
--	---------------



Bonnet, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	--------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R polished, Rust, Acceptable	0,00
--	------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Spoiler R, Scratch(es), It - Spot repair	115,56
--	--------



Wheel arch cover F L, Deformed / Strained, Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Roof, Scratch(es), LI - Repair and paint (complete)	577,80
---	--------



