



AUDI A1 SPORTBACK: 1LLJ735

Vinnumber:	WAUZZZ8X1GB045172	Versionname:	1.6 TDI 85KW
First Registrationdate:	20/10/2015	Fiscalpower:	
Expertise Mileage:	52384	Power Kw:	85
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1714
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/60/15/94 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1381,30
Outer door handle F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68



Roof, Chemical pollution, LI - Repair and paint (complete) 385,20



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display
Bumper R, Scratch(es), Acceptable 0,00

No pictures to display
Bonnet, Chemical pollution, LI - Repair and paint (complete) 232,06



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display