



**MERCEDES C BREAK: 1KNL880**

Vinnumber:	<b>WDD2052361F203652</b>	Versionname:	<b>1.6 C 180 BLUETEC AVANTGARDE</b>
First Registrationdate:	<b>3/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>176580</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>SERVICE A DANS 17100 KM</b>	Parking lot:	<b>3209</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/98 V None</b>				
Summer tyres:	Fr.L.	<b>Continental: 1 mm</b>	Fr.R.	<b>Continental: 1 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>
<b>225/55/17/98 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Continental: 1 mm</b>	Fr.R.	<b>Continental: 1 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>2795,44</b>
<b>Bumper F, Scratch(es), LI - Repair and paint (complete)</b>			<b>211,80</b>



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Interior, Smell, Ozone treatment

152,58



Roof, Dent(s), PDR - Paintless dent repair

63,00



Windscreen, Stone chip(s), E - Replace

0,00



Seat cover F L, Stain, Cleaning

25,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (partial)

220,18



Bonnet, Stone chip(s), Tu - Touch up

50,00



Rearlight R, Broken, E - Replace

144,00



Rearlight R, Broken, L - Replace

115,00



Interior, Dirty, Chemical cleaning

175,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper trim R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

380,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre F L, Worn, E - Replace

132,00



Tires, Out of tolerance, P - Check

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Lock stricker R, Strained , Forfeit

40,00



Mirror side blinker R, Broken, E - Replace

30,00



Wing F R, Scratch(es), It - Spot repair

115,56

wing F R, Scratch(es), It - Spot repair

115,56



Alloy rim R L, Scratch(es), Acceptable

0,00



Tyre F R, Worn, E - Replace

132,00



Sill trim R, Scratch(es), It - Spot repair

115,56

