



MERCEDES CLA: 1KSJ227

Vinnumber:	WDD1173121N240048	Versionname:	1.5 CLA 180 CDI
First Registrationdate:	23/06/2015	Fiscalpower:	
Expertise Mileage:	133299	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	240JOURS	Parking lot:	3821
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	No Tow bar
GPS storage		
GPS storage	SD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Manual climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal			
Summer tyres:	Fr.L. Bridgestone: 6 mm	Fr.R. Bridgestone: 6 mm	
	Re.L. Bridgestone: 5 mm	Re.R. Bridgestone: 5 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2331,32

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35




Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, LI - Repair and paint (complete) 404,20



Headlight R, Scratch(es), E - Replace 396,00



Floor covering F L, Burned, Smart repair 64,32



Bumper R, Bad repair, LI - Repair and paint (complete) 211,80



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Roof, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display